

# Clermont County Sheriff Office

## Traffic Crash Report

Local Report # 1500023256	Severity PDO	Private Property	Photos Taken	NCIC # 01300
Reporting Agency Clermont County Sheriff Office	# Units	Unit Error 98	Date and Time of Crash 03/13/2015 22:10	
City, Village, Township Village	Name (of City, Village or Township) Chilo	County # 13	Latitude 38.79	Longitude -84.15

### Crash Occured On

Route Type Federal US Rou	Route Number 52	Road Type	Road Prefix	Road Name
------------------------------	--------------------	-----------	-------------	-----------

### At / Reference

Reference Point House Number	Distance from Referance	Distance Type	Direction to	Reference Route Type	Reference Route Number 222
Reference Prefix	Reference Road Name	Road Contour Straight Level	Road Condition Primary Wet	Secondary:	

### Police Action

Dispatch # 201500023256	Report Date 03/13/2015 22:16	State Reportable
Time of Dispatch 22:16	Time of Arrival 22:25	Time of Clearance 22:42
Reporting Officer's Name Donovan Dominick	Officer Badge 2322	

### Manner of Collision or Impact

Not Collision Between Two Motor Vehicles in Transport

### Diagram

Lane Direction	Divided Highway Undivided	
School Related No	Work Related No	Workers Present No
Work Zone Type	Work Zone Locatic	

### Weather

Rain

### Narrative

Unit 1 was traveling east bound when a two deer ran into the front driver side and driver side fender, door and bed of his truck causing damage

# Clermont County Sheriff Office

## Traffic Crash Report

Unit Information				
<b>Owner First</b>	<b>Owner Middle</b>	<b>Owner Last</b>	<b>LP State</b>	<b>LP #</b>
Walter	D.	Toller	0	RS369182
<b>Owner Address</b>	<b>Owner City</b>	<b>Owner State</b>	<b>Owner Zip</b>	<b>Owner Phone #</b>
580 Main ST	Ripley	OH	45167	
<b>Vehicle Year</b>	<b>Vehicle Make</b>	<b>Vehicle Model</b>	<b>Vehicle Color</b>	<b>VIN</b>
2001	Dodge	Pickup	Blue	
<b>Insurance Name</b>	<b>In Emergency Response</b>	<b>Speed Dected</b>	<b>Unit Speed</b>	<b>Posted Speed</b>
General Auto Insuran	2	0	40	45
<b>Non-Motorist</b>	<b>Action</b>	<b>Towed By</b>	<b>Damage Scale</b>	<b>Vehicle Direction</b>
	Struck			4
<b>Unit Type</b>	<b>Point of Impact</b>	<b>Vehicle Defects</b>	<b>Pre-crash Action</b>	
Pickup	Right Side		Straight Ahead	
<b>Contributing Circumstances</b>		<b>Secondary Circumstances</b>	<b>Sequence of Events 1</b>	<b>Sequence of Events 2</b>
None			Animal - Deer	
<b>Sequence of Events 3</b>	<b>Sequence of Events 4</b>	<b>Sequence of Events 5</b>	<b>Sequence of Events 6</b>	
<b>Carrier Name</b>	<b>Carrier Phone</b>	<b>US DOT</b>	<b>HM Class</b>	<b>HM Placard</b>
			0	
<b>Carrier Address</b>	<b>City</b>	<b>State</b>	<b>Zip</b>	

# Clermont County Sheriff Office

## Traffic Crash Report

People Information				
Unit Number: 1				
First	Middle	Last	Type	
Walter	D.	Toller	Owner/Driver	
Address	City	State	Zip	Contact Number
580 Main ST	Ripley	OH	45167	
DOB	Gender	DL State	DL Number	Charge Number
6/20/72	M	0	RS369182	
Injured Taken To	Transported By	Seating Position	Ejected	Charge Description
		Front Seat, Left Side	1	
Air Bag	Trapped	Safety Equipment Used	Condition	Citation Number
N	Not Trapped	Shoulder and Lap Belt Us	Apparently Normal	
Injuries	Alcohol Test	Alcohol Test Status	Drug Test	Drug Test Status
No Injury / None Reported	None		None	None Given

People Information				
Unit Number: 1				
First	Middle	Last	Type	
Sandra		Toller	Occupant	
Address	City	State	Zip	Contact Number
580 Main ST	Ripley	OH	45167	
DOB	Gender	DL State	DL Number	Charge Number
5/23/72	F	0		
Injured Taken To	Transported By	Seating Position	Ejected	Charge Description
		Front Seat Right Side	1	
Air Bag	Trapped	Safety Equipment Used	Condition	Citation Number
N	Not Trapped	Shoulder and Lap Belt Us	Apparently Normal	
Injuries	Alcohol Test	Alcohol Test Status	Drug Test	Drug Test Status
No Injury / None Reported	None	None Given	None	None Given

People Information				
Unit Number: 1				
First	Middle	Last	Type	
Brianna		Toller	Occupant	
Address	City	State	Zip	Contact Number
580 Main ST	Ripley	OH	45167	
DOB	Gender	DL State	DL Number	Charge Number
9/5/99	F	0		
Injured Taken To	Transported By	Seating Position	Ejected	Charge Description
		Second Seat, Left Side	1	
Air Bag	Trapped	Safety Equipment Used	Condition	Citation Number
N	Not Trapped	Shoulder and Lap Belt Us	Apparently Normal	
Injuries	Alcohol Test	Alcohol Test Status	Drug Test	Drug Test Status
No Injury / None Reported	None	None Given	None	None Given

Case Number: 2015-23256

Date: 3-13-15

Location: US 52 + SR 222

Description:

