

# Clermont County Sheriff Office

## Traffic Crash Report

Local Report #  Severity  Private Property  Photos Taken  NCIC #

Reporting Agency  # Units  Unit Error  Date and Time of Crash

City, Villiage, Township  Name (of City, Villiage or Township)  County #  Latitude  Longitude

### Crash Occured On

Route Type  Route Number  Road Type  Road Prefix  Road Name

### At / Reference

Reference Point  Distance from Referance  Distance Type  Direction to  Reference Route Type  Reference Route Number

Reference Prefix  Reference Road Name  Road Contour  Road Condition   
Secondary:

### Police Action

Dispatch #  Report Date  State Reportable   
Time of Dispatch  Time of Arrival  Time of Clearance   
Reporting Officer's Name  Officer Badge

### Manner of Collision or Impact

Lane Direction  Divided Highway   
Undivided

School Related  Work Related  Workers Present

Work Zone Type  Work Zone Locatic

Weather

### Diagram

### Narrative

Unit was traveling south bound on SR 232 when a deer entered the roadway from the east and struck the vehicle

# Clermont County Sheriff Office

## Traffic Crash Report


Unit 1 Information				
<b>Owner First</b>	<b>Owner Middle</b>	<b>Owner Last</b>	<b>LP State</b>	<b>LP #</b>
Nicole	Riley	Abner	0	UD154018
<b>Owner Address</b>	<b>Owner City</b>	<b>Owner State</b>	<b>Owner Zip</b>	<b>Owner Phone #</b>
3666 SR 125	Bethel	OH	45106	girlnra@yahoo.com
<b>Vehicle Year</b>	<b>Vehicle Make</b>	<b>Vehicle Model</b>	<b>Vehicle Color</b>	<b>VIN</b>
2014	Chevrolet	Cruze	Red	1G1PC5SB9E7320913
<b>Insurance Name</b>	<b>In Emergency Response</b>	<b>Speed Dected</b>	<b>Unit Speed</b>	<b>Posted Speed</b>
GEICO	2	0	55	55
<b>Non-Motorist</b>	<b>Action</b>	<b>Towed By</b>	<b>Damage Scale</b>	<b>Vehicle Direction</b>
	Struck			3
<b>Unit Type</b>	<b>Point of Impact</b>	<b>Vehicle Defects</b>	<b>Precrash Action</b>	
Compact	Left Fron		Straight Ahead	
<b>Contributing Circumstances</b>		<b>Secondary Circumstances</b>	<b>Sequence of Events 1</b>	<b>Sequence of Events 2</b>
Other Non-Motorist			Animal - Deer	
<b>Sequence of Events 3</b>	<b>Sequence of Events 4</b>	<b>Sequence of Events 5</b>	<b>Sequence of Events 6</b>	
<b>Carrier Name</b>	<b>Carrier Phone</b>	<b>US DOT</b>	<b>HM Class</b>	<b>HM Placard</b>
			0	
<b>Carrier Address</b>	<b>City</b>	<b>State</b>	<b>Zip</b>	

People Information				
Unit Number: 1				
<b>First</b>	<b>Middle</b>	<b>Last</b>	<b>Type</b>	
Nicole	Riley	Abner	Owner/Driver	
<b>Address</b>	<b>City</b>	<b>State</b>	<b>Zip</b>	<b>Contact Number</b>
3666 SR 125	Bethel	OH	45106	girlnra@yahoo.com
<b>DOB</b>	<b>Gender</b>	<b>DL State</b>	<b>DL Number</b>	<b>Charge Number</b>
10/6/94	F	0	UD154018	
<b>Injured Taken To</b>	<b>Transported By</b>	<b>Seating Position</b>	<b>Ejected</b>	<b>Charge Description</b>
		Front Seat, Left Side	1	
<b>Air Bag</b>	<b>Trapped</b>	<b>Safety Equipment Used</b>	<b>Condition</b>	<b>Citation Number</b>
N	Not Trapped	Unknown Safety Equipme	Apparently Normal	
<b>Injuries</b>	<b>Alcohol Test</b>	<b>Alcohol Test Status</b>	<b>Drug Test</b>	<b>Drug Test Status</b>
No Injury / None Reported	None		None	None Given

OHIO TRAFFIC ACCIDENT – DIAGRAM/NARRATIVE CONTINUATION

OH-2 (Rev. 1/82)

LOCAL REPORT NUMBER 201500047079	REPORTING AGENCY CCSO	DATE OF ACCIDENT M 5 10 22 Y 15
IN COUNTY OF Clermont	ACCIDENT LOCATION 2599 SR 232	



OFFICER'S SIGNATURE  
*[Handwritten Signature]*

BADGE NO.  
2520