

# Clermont County Sheriff Office

## Traffic Crash Report

Local Report #       Severity       Private Property       Photos Taken       NCIC #

Reporting Agency       # Units       Unit Error       Date and Time of Crash

City, Village, Township       Name (of City, Village or Township)       County #       Latitude       Longitude

### Crash Occurred On

Route Type       Route Number       Road Type       Road Prefix       Road Name

### At / Reference

Reference Point       Distance from Reference       Distance Type       Direction to       Reference Route Type       Reference Route Number

Reference Prefix       Reference Road Name       Road Contour       Road Condition  
 Primary       Secondary:

### Police Action

Dispatch #       Report Date       State Reportable

Time of Dispatch       Time of Arrival       Time of Clearance

Reporting Officer's Name       Officer Badge

### Manner of Collision or Impact

### Diagram

Lane Direction       Divided Highway

School Related       Work Related       Workers Present

Work Zone Type       Work Zone Locatic

Weather

### Narrative

THE OPERATOR OF UNIT #1 WAS SOUTH ON IR 275 APPROACHING MP 58.8. UNIT #1 WAS TOYOTA 4RUNNER AND IT WAS PULLING A TRAILER. THE TRAILER BEGAN TO FISHTAIL AND THE TRAILER OVERTURNED SEPERATING FROM THE 4RUNNER AND SHEARED THE TRAILER BALL AND BREAKING THE SAFETY CHAINS AND COMING TO REST ON IR 275.

# Clermont County Sheriff Office

## Traffic Crash Report

Unit 1 Information				
<b>Owner First</b>	<b>Owner Middle</b>	<b>Owner Last</b>	<b>LP State</b>	<b>LP #</b>
ROBERT		PEMBERTON	KY	P2402719
<b>Owner Address</b>	<b>Owner City</b>	<b>Owner State</b>	<b>Owner Zip</b>	<b>Owner Phone #</b>
1200 ROCKBRIDGE	LEXINGTON	KY	50515	
<b>Vehicle Year</b>	<b>Vehicle Make</b>	<b>Vehicle Model</b>	<b>Vehicle Color</b>	<b>VIN</b>
2003	Toyota	4Runner	Green, Dark	5TDBT44A43S148163
<b>Insurance Name</b>	<b>In Emergency Response</b>	<b>Speed Dected</b>	<b>Unit Speed</b>	<b>Posted Speed</b>
STATE FARM	2		1 60	65
<b>Non-Motorist</b>	<b>Action</b>	<b>Towed By</b>	<b>Damage Scale</b>	<b>Vehicle Direction</b>
	Non-contact	GRAYS		1
<b>Unit Type</b>	<b>Point of Impact</b>	<b>Vehicle Defects</b>	<b>Precrash Action</b>	
Sport utility Vehicle	Left Side		Straight Ahead	
<b>Contributing Circumstances</b>		<b>Secondary Circumstances</b>	<b>Sequence of Events 1</b>	<b>Sequence of Events 2</b>
Failure to Control			Struck by Falling, Shifting	Separation of Units
<b>Sequence of Events 3</b>	<b>Sequence of Events 4</b>	<b>Sequence of Events 5</b>	<b>Sequence of Events 6</b>	
<b>Carrier Name</b>	<b>Carrier Phone</b>	<b>US DOT</b>	<b>HM Class</b>	<b>HM Placard</b>
			0	
<b>Carrier Address</b>	<b>City</b>	<b>State</b>	<b>Zip</b>	

People Information				
Unit Number: 1				
<b>First</b>	<b>Middle</b>	<b>Last</b>	<b>Type</b>	
ROBERT		PEMBERTON	Owner/Driver	
<b>Address</b>	<b>City</b>	<b>State</b>	<b>Zip</b>	<b>Contact Number</b>
1200 ROCKBRIDGE	LEXINGTON	KY	50515	
<b>DOB</b>	<b>Gender</b>	<b>DL State</b>	<b>DL Number</b>	<b>Charge Number</b>
1/4/52	M	KY	P2402719	
<b>Injured Taken To</b>	<b>Transported By</b>	<b>Seating Position</b>	<b>Ejected</b>	<b>Charge Description</b>
		Front Seat, Left Side	1	
<b>Air Bag</b>	<b>Trapped</b>	<b>Safety Equipment Used</b>	<b>Condition</b>	<b>Citation Number</b>
N	Not Trapped	Shoulder and Lap Belt Use	Apparently Normal	
<b>Injuries</b>	<b>Alcohol Test</b>	<b>Alcohol Test Status</b>	<b>Drug Test</b>	<b>Drug Test Status</b>
No Injury / None Reported	None		None	None Given